



174284B5



PROJECT

TYPE

NOTES

QUANTITY

DATE












Pendant rod suspension made from aluminium; can be cut and adjusted as desired max. 1950 mm; for ceiling surface mounting; surface Black Matt; powder coated, matt texture; RAL 9005; opal PMMA diffuser; PCB 3-step binning; phase-cut dim; light colour 3000 K; binning initial MacAdam \leq 3 SDCM; CRI \geq 90; CRI (Colour Rendering Index) \geq 90; 220 - 240 V; degree of protection IP20; Class 1; driver included; light source replaceable by Wever & Ducré or by a professional with explicit authorization; control gear replaceable by end-user;



GENERAL

| Ceiling |
|--------------------------------|
| Surface |
| Black Matt |
| RAL 9005 ^a |
| IP20 |
| Interior |
| 730 lm |
| CIE flux code: 11 35 66 50 100 |

LED

| 3000 K | |
|--------------------------|--|
| CRI ≥ 90 | |
| L80 / 50000h | |
| initial MacAdam ≤ 3 SDCM | |
| | |

OPTICAL

Opal

ELECTRICAL

PHYSICAL

| diameter 9 mm |
|----------------|
| height 1000 mm |
| 0.43 kg |

^a Colour may deviate slightly due to production conditions.



174284B5



Maintenance Factor

| Operating Time [h] | 10.000 | 20.000 | 30.000 | 40.000 | 50.000 |
|--------------------|--------|--------|--------|--------|--------|
| LLMF | 0.98 | 0.96 | 0.94 | 0.93 | 0.91 |
| LSF | 1 | 1 | 1 | 1 | 1 |

| MF | LMF × RSMF × LLMF × LSF | RSMF ^a | Room Surface Maintenance Factor | |
|------|------------------------------|-------------------|---------------------------------|--|
| MF | Maintenance Factor | LLMF | Lamp Lumens Maintenance Factor | |
| LMFa | Luminaire Maintenance Factor | LSF | Lamp Survival Factor | |

^aAccording to "CIE 97, Maintenance of indoor electric lighting systems", 2005, ISBN 3-900-734-34-8. The values must be determined by the planner.

MOUNTING ACCESSORIES

FINLIN Cover Plate Adapter

| Туре | Colour | Ø·H (MM) | ltem number |
|-----------------------|--------|----------|-------------|
| for concrete housings | Black | 100.3 | 900194B0 |